DEPARTMENT OF TRANSPORTATION

FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

														Date			
Inspector's Name		In		Inspecto			ctor's ID No.	Report No). 	уу	mm	dd					
Glenister, Roland								31	965	45		2019	07	30			
Railroad/Company Name & Address							R/C	Divis	ion		RR/Co. Re	o. Representative (Receipt Acknowledged)					
DENTON COUNTY TRANSPORTATION AUTHORITY							R	SYS	TEM		Name	Steve Wel	ch				
640							RR/Co.	C-1-1	ivision	Title Deputy General Manas							
State HWY 121 Business							Code DCTA				Title	Deputy General Manager					
Lewisville		TX	7:	75057				515	SYSTEM			steve.welch@firstgroup.com					
											Signature						
From: City DENTON			Codes 1840	0	Destination City & County						Codes	de			-		
State TX		48		City							From Longitude						
County DENTON			C121 County									To Latitude					
Mile Post: From 0	727.10	To 072	21.78	Insp	ection Po	110	(EVIEW BLVD(414690Y)-SY 795445V)				AMORE	To Longitude					
Activity Code:	222	GIIR	ENSS	HG	CS	THI	TRP	,									
Units:	1	1	1	1		1	1		1								
Sub Units:	0	11	18	60		12	0		8	8							
Item Initials/Milepo	ment/Track #	Type/Kind	49 CFR	Z/ Defe	ct Subr	ule		Speed C	lass T	rain #/Site	Sì	VFR*	RCL**	# of	Activity		
USC														Occ.***	Code		
1												1	N	N	0	222	
Description - [** C	omment to R	Railroad/Con	npany **]		J.									.!			
On July 30, 2019 at County Transportat	t 10:30 AM,	I conducted	an Federal														
continued compliance with 49 Code of Federal Regulations (CFR) Parts 222 Subpart B & C, Part 234 Subpart E & F, FRA Guide for Preparing Crossing Inventory forms dated July 19, 2016, General Code of Operating Rules (GCOR), DCTA Operating/Safety Rules, Timetables, Bulletins, and Special Instructions. Additionally to																	
Forms dated July 19 inspect for complia																	
City of Denton TX	QZ filed wit	h FRA Ref#	THR-00088	89 estal	blished	and effec	tive June 6	, 2011.	Highway	-Rail	Grade Cros	sings (HRG	iC) ir	i, 2012 ic ispected v	v.) regar vithin th	is	
corridor (continue)								,				<i>\(\)</i>		1			
Seal Applied	Se	al Removed	Hazard Class			U	UN/NA ID										
Violation Recommend	Yes	✓ No	_atitude:	 atitude:				Longitude:									
Written Notification to FRA of Remedial A	Required	d Option	✓ Optional Railroad Action					Date(mm/	dd/yyy	/y):	Comments on back?				ck?		
Tar of Remedial A	1011115.			<u>. </u>													

OMB Approval No.: 2130-0509

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspec	tor's ID No.	Repo	rt No.	Report	Date	;				`		,										
319	965		45	7/30/	2019)																
Item	Initials/Milepo	ost	Equipme	nt/Track	c#	Type/Kind	49 CFR/ USC	Defect	Su	brule			S	peed	Class	Train	#/Site	e	SNFR*	RCL**	# of Occ.***	Activity Code
2																			N	N	0	ENSS
Descr	iption - [** C	omme	nt to Rail	lroad/C	omp	any **]		ı					- 1									I
	nue) were La																					
	14678S), Dur																					
	found during will also prov															ty) and	DC	I A official(s) for na	andling c	n July 30	J, 2019.
Seal A		100 0		тторе		Removed	- QZ 111	эрссион		1111010	_	zard Clas		3 10 11				UN/NA ID				
	• •																					
Violati	ion Recommend	led		Yes		✓ No				Latitu	ude:]	Longitude:				
	n Notification to of Remedial A		is:	Requ	ired	✓ Optio	onal R	ailroad Ao	ction	Code			I	Date(n	nm/dd/	уууу):				Comm	ents on ba	ck?
Item	Initials/Milepo	ost	Equipme	nt/Track	c#	Type/Kind	49 CFR/ USC	Defect	Su	brule			S	peed	Class	Train	#/Site	e	SNFR*	RCL**	# of Occ.***	Activity Code
3																			N	N	0	GIIR
Descr	iption - [** C	omme	nt to Rail	lroad/C	omp	any **]																
inspector Rd. (control August I inspector)	tory Reporting tion: Colorad Elosed). The cost 15, 2017. ected for the page 34 Subpart E	lo Blvo orrect oroper	d is listed U.S. DO' placemen	in the T for C	City olora nain	of Dentorado Blvd i	n Notice s 414679 f Highwa	of Quiet OY listed ny-Rail C	Zon	e Esta ectly	iblisl in th	hment a ne Lette	and t	he QZ Affirn	Z Calc nation	ulatior (LOA	she) da	ets as U.S. I ted August 1	OOT 414 0, 2017	4680T w received	hich is S I by FRA	pencer
Seal Applied Seal Removed							Hazard Class							UN/NA ID								
Violati	ion Recommend	ded		Yes		✓ No				Latitu	ude:]	Longitude:				
	n Notification to of Remedial A		is:	Requ	ired	✓ Optio	onal R	ailroad Ao	ction	Code			I	Date(m	nm/dd/	уууу):				Comm	ents on ba	ck?
Item	Initials/Milepo	ost	Equipme	nt/Track	c#	Type/Kind	49 CFR/ USC	Defect	Su	brule			S	peed	Class	Train	#/Sit	e	SNFR*	RCL**	# of Occ.***	Activity Code
4																			N	N	0	HGCS
Descr	iption - [** C	omme	nt to Rail	lroad/C	omp	any **]																
No de	efects on syste	ems ins	pected.																			
Seal A	nnlied				Seal	Removed					Наз	zard Clas	SS					UN/NA ID				
Searra	ppnea				Star	Tromo vou					1141	Lura Ora						O.W.W.T.D				
Violati	ion Recommend	led		Yes		✓ No				Latitu	ude:							Longitude:				
	n Notification to of Remedial A		is:	Requ	ired	✓ Optio	onal R	ailroad Ao	ction	Code			I	Date(n	nm/dd/	уууу):				Comm	ents on ba	ck?
							•															

DEPARTMENT OF TRANSPORTATION INSPECTION REPORT FEDERAL RAILROAD ADMINISTRATION (FRA) OMB Approval No.: 2130-0509 Inspector's ID No. Report No. Report Date 31965 7/30/2019 45 Type/Kind 49 CFR/ Defect Subrule Class Train #/Site SNFR* Item Initials/Milepost Equipment/Track # Speed RCL* # of Activity USC Occ.* Code 0 5 Ν THI N Description - [** Comment to Railroad/Company **] I observed several DCTA trains including 101, 102, 104/321, 105, 132 displaying head/ditch lights, and either silenced train horns account effective QZ or blowing the proper train horn pattern acknowleging employees working near the tracks in compliance with Federal Regulations (CFR) Part §222.21 (When must a locomotive horn be used) and 49 CFR Part §229.125 Headlights and auxiliary lights. No defects. Seal Applied Seal Removed Hazard Class UN/NA ID Violation Recommended Latitude: Longitude: Yes **✓** No Written Notification to Railroad Action Code Date(mm/dd/yyyy): Comments on back? Required **✓** Optional FRA of Remedial Action is:

Description - [** Comment to Railroad/Company **]

Equipment/Track #

Initials/Milepost

Item

6

Type/Kind 49 CFR/

USC

Defect

Inspected for evidence of well worn paths and found two locations at Brinker Rd and Colorado Blvd where cyclists and or pedestrian take short cuts to cross tracks placing themselves at risk of being struck by on coming train or motorists. City official notified on July 30, 2019. FRA also met with DCTA-CTC and City of Denton officials for safety briefing and a discussion at Brinker Rd (414686J) to address any questions and or concerns regarding FRA Quiet Zone review and inspection

Speed

Class Train #/Site

Subrule

process.											
Seal Applied	Seal Removed	Hazard Class	UN/NA ID								
Violation Recommended Yes	✓ No Latitu	ıde:	Longitude:								
Written Notification to FRA of Remedial Action is:	uired Optional Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?								

RCL**

N

#of

0

Occ.*

Activity

Code

TRP

SNFR*

N